

YEAR
1991 – 95

MODEL
LEGEND

VIN APPLICATION
ALL

BULLETIN NO.
94-015



Acura/Bose Amplifier Remanufacturing Program

COVERAGE

Use a remanufactured Acura/Bose amplifier for warranty and customer-pay repairs.

PROCEDURE

When a customer calls or comes in with an audio complaint, obtain the following information:

- Name
- VIN
- Specific complaint
- Retail delivery date of the car
- Mileage

Diagnose the problem. Refer to service bulletin 87-015, *Audio Unit Exchange Program*, for diagnostic procedures. If you determine the amplifier is defective, order a remanufactured unit and schedule an appointment for replacement of the amplifier.

Ordering

Remanufactured Acura/Bose amplifiers can be ordered on a Scheduled Stock Order, Daily Parts Order, or an Urgent Parts Order.

The part numbers for the remanufactured amplifier and the core will both be on the shipper document, along with their respective values. The remanufactured part number ends with "RM." The core part number ends with "CO."

Core return and core deposit credits will be handled through the Order Adjustment Return (O.A.R.) system. Refer to Parts Information Bulletin B94-0035, *Remanufactured Bose Amplifier Program*, for the procedure.

PARTS INFORMATION

Acura/Bose remanufactured amplifier:

- 1991 – 92 Legend 4-door – 39186-SP0-A02RM
- 1991 – 92 Legend 2-door – 39186-SP1-A02RM
- 1993 – 95 Legend 4-door – 39186-SP0-A03RM
- 1993 – 95 Legend 2-door – 39186-SP1-A03RM

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Technical Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

Operation number: 010112

Flat rate time: 0.9 hour

Failed P/N: Use AHM part number of amplifier being replaced.

Defect code: 042

Contention code: F02